

**Gainsborough Studios  
South-east Block  
Progress report 002**



## **South Block**

Structural engineer works -100 %  
Scaffold erecting -100% Finished on 23.04 like per program  
Removing old render-50%  
Remedial works -0 %  
Reinstall new Soltherm System-0%  
Replace balconies decking-0%  
Replace balconies cladding -0%

## **East Block**

Scaffold erecting -30%  
Structural engineer works -50%  
Removing old render-0%  
Reinstall new Soltherm System-0%  
Replace balconies decking-0%  
Replace balconies cladding -0%